

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY REGION 10

81eph WA 6906 8993 5f

1200 Sixth Avenue Seattle, Washington 98101

AUG 0 9 1993

Reply To

Attn Of: HW-104

Jim Pankanin
PRC Environmental Management, Inc.
1411 Fourth Avenue
Suite 720
Seattle, Washington 981019

Re: Contract No. 68-W9-0009, TES 12

Work Assignment No. R10054 EPA I.D. No. WAD009036906

Dear Mr. Pankanin:

Enclosed is a report dated July 10, 1993 from Niedermeyer-Martin regarding the Ridgefield Brick and Tile facility. The report was made in response to the Operations and Maintenance inspection (O&M) conducted by PRC for EPA.

Please submit a copy of the final PRC O&M report and the enclosed report to your subcontractor Robert Farrell for review. I would like to receive a draft letter report from Mr. Farrell within approximately six weeks providing his opinion of RBT's proposed monitoring plan. Telephone conferences regarding this issue would be welcome, and I can be reached at (206) 553-0684.

Thank you for your assistance in this matter.

Sincerely,

Marcia L. Bailey, D.Env. Environmental Scientist

RCRA Compliance Section

Enclosure

cc: Vicky Tapang (w/o enc.)

Betty Wiese (w/o enc.)

